



Campaign Bulletin 100011

This bulletin is a follow-up to campaign bulletin 090010, which added updated instructions on how to operate the machines equipped with a hydraulically driven welder generator. The affected machines for this bulletin include additional models, S-100, S-105, S-120, S-125, Z-80 and Z-135, which were not included in Campaign Bulletin 090010.

Date: December 15, 2010
Subject: Braking on Slopes
(On Machines Equipped with a Hydraulically Driven Welder Generator or Welder Ready Package)

Models and Serial Numbers Affected:

S-40 and S-45: 26 to 15690
S-60 and S-65: 654 to 9153
S-80 and S-85: 1 to 8255
S-100 and S-105: 101 to 810
S-120 and S-125: 101 to 2798
Z-60: 4001 to 9960
Z-80: 1 to 2572
Z-135: 101 to 1139

Allowable Hours: 2 hours

Issue:

Genie Industries, has determined that under certain circumstances, some machines equipped with a hydraulically driven welder/generator or welder ready package may experience reduced hydraulic braking ability on slopes. **Reduced braking ability could result in the machine running away on a slope.**

Action Required: This bulletin requires the following modifications:

- Addition of a pressure switch in the hydraulic system on all affected machines.
 - Replacement of the SX module on S-40, S-45, S-60, S-65, S-80, S-85 and Z-60 models.
1. Locate all machines equipped with a hydraulically driven welder generator or welder ready package within the serial number ranges above.

Note: Enclosed is a machine list report. If you have a machine in the list that is not equipped with a hydraulically driven welder generator or welder ready package, fill out the enclosed machine update form and return to Genie Engineering Standards Department. No further action is necessary.

e-mail: AWP.Engineeringstandards@terex.com
Fax No.: 425-882-9260

**FAILURE TO COMPLETE THIS BULLETIN MAY
RESULT IN DEATH OR SERIOUS INJURY.**



Campaign Bulletin 100011

2. Completely fill out the Parts Order Form and fax to Genie's Parts Department to receive, at no cost, a Pressure Switch / SX module kit, with installation instructions for your machine.

Installation must take place as soon as possible but no later than 30 days from receipt of parts.

3. Fill out and sign the completion form included with the instructions in the parts kit and fax to Genie's warranty department to verify that this campaign bulletin has been completed.

Warranty:

The labor and travel miles required to perform this inspection and installation are covered under the provisions of our warranty agreement. Labor for each affected machine will be paid at a rate of \$60.00 U.S. per hour and travel at a rate of \$.50 U.S. per mile, converted into the currency of the appropriate country at the time of payment.

If you are the owner of an affected machine and are not an authorized Genie dealer, please contact your nearest Genie dealer for assistance with this campaign bulletin. Only Genie Authorized Dealers will be reimbursed for labor or any other costs associated with this bulletin under the provisions of our standard warranty terms and conditions.

Genie and ANSI requires that the seller of a Genie machine report to Genie the model and serial number of each machine sold, as well as the name, address, and telephone number of the new owner, within 60 days of the sale. OSHA and ANSI also require that the manufacturer's campaign bulletins be completed. It is your responsibility to communicate this important information to all machine owners and applicable branches. If you require additional copies of this bulletin or have any questions, please contact Genie's service department at:

Unites States	800-536-1800
Canada	425-881-1800
Europe	+31 653 221 908
Australia	61 733751660
All other locations	001-425-881-1800

Enclosures:

Machine List Report
Machine Update Form
Owner Update Form
Parts Order Form

**FAILURE TO COMPLETE THIS BULLETIN MAY
RESULT IN DEATH OR SERIOUS INJURY.**



Campaign Bulletin 100011

New Owner Update Form
(for updating machine owner information only)

Genie and ANSI requires that the seller of a Genie machine report to Genie the model and serial number of each machine sold, as well as the name, address, and telephone number of the new owner, within 60 days of the sale.

- **If you have sold a machine, list the complete model and serial number** (example: S40-6367, S4507-12455, S60-8650, S6003-9056, S60HC07-19039, S60TX09-20283, S80-2369, S8009-8106 or Z6004-4630) and the name, address and phone number of the new owner

New Owner Information:

	Machine 1	Machine 2	Machine 3
Model*	_____	_____	_____
Serial Number*	_____	_____	_____
Owner Name*	_____	_____	_____
Address 1*	_____	_____	_____
Address 2	_____	_____	_____
City/State/Zip*	_____	_____	_____
Phone Number*	_____	_____	_____
Contact Person	_____	_____	_____

* *Required fields.*

Seller Information:

Date: _____

Company Name: _____

Account #: _____

Address: _____

(street) _____

(city) _____

State, zip code _____

Phone #: _____

- List any machines that could not be inspected or repaired because of the following:

Model & Serial Number	Scrapped	Exported	Stolen	Others (explain)
_____	-	-	-	-
_____	-	-	-	-
_____	-	-	-	-
_____	-	-	-	-

Fax to: United States 877-738-7530
 Canada 425-498-7530
 All other locations 001-425-498-7530



Campaign Bulletin 100011

Parts Order Form

Fax this form to Genie Industries to receive the indicated *SX Module/Pressure Switch Kit* for your machine. List the model and serial number of each affected machine.

Model	Serial Range	Kit P/N
S-40 & S-45	- from 26 to 7000	- T106392
	- from 7001 to 15690	- 146338
S-60 & S-65	- from 654 to 9153	- 147572
S-80 & S-85	- from 1 to 3081	- T106393
	- from 3082 to 7999	- 146337
	- from 8000 to 8255	- 146286

Model	Serial Range	Kit P/N
S-100 & S-105	- from 101 to 810	- 146445
S-120 & S-125	- from 101 to 2798	- 146445
Z-60/34	- from 4001 to 4550	- 147822
	- from 4551 to 9960	- 146339
Z-80/60	- from 1 to 2572	- 146447
Z-135/70	- from 101 to 1139	- 146440

- **Please list the complete model and serial number** (example: S40-6367, S4507-12455, S60-8650, S6003-9056, S60HC07-19039, S60TX09-20283, S80-2369, S8009-8106 or Z6004-4630).

Model & Serial Number	-	Kit P/N
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____

Model & Serial Number	-	Kit P/N
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____
_____	-	_____

Date: _____
 Company Name: _____
 Ordered by: _____
 Account # (If applicable): _____
 Address: _____
 (street): _____
 (city): _____
 (state, zip code): _____
 Phone: _____

Send Parts to: (If you would like to send parts to a different location)
 Company Name: _____
 Attn: _____
 Account # (if applicable): _____
 Address: _____
 (street): _____
 (city): _____
 (state, zip code): _____
 Phone: _____

Fax to:	United States	888-274-6192
	Canada	425-556-8659
	All other locations	001-425-556-8659



Campaign Bulletin 100011

Machine Update Form

The machines listed below are not equipped with a hydraulically driven welder generator or a welder ready option and therefore is not affected by the Campaign Bulletin.

Owner Information:

Date: _____
Company Name: _____
Account #: _____
Address: _____
(street) _____
(city) _____
State, zip code _____
Phone #: _____

Table with 4 columns: Model, Serial Number, Model, Serial Number. Multiple rows for data entry.

Email to: AWP.EngineeringStandards@terex.com

Fax to: 425-882-9260