

SUSPECT ASBESTOS-CONTAINING MATERIALS

As specified in the U.S. Environmental Protection Agency document entitled, "*Managing Asbestos In Place - A Building Owner's Guide to Operations and Maintenance Programs for Asbestos-Containing Materials*", dated July 1990, the following materials are considered suspect asbestos-containing materials:

Cement Pipes	Elevator Brake Shoes
Cement Wallboard	HVAC Duct Insulation
Cement Siding	Boiler Insulation
Asphalt Floor Tile	Breeching Insulation
Vinyl Sheet Flooring	Duct Flexible Connectors
Vinyl Floor Tile	Cooling Towers
Flooring Backing	Pipe Insulation
Construction Mastics	Heating/Electrical Ducts
Acoustical/Decorative Plaster	Electrical Panel Partitions
Textured Paints/Coatings	Electrical Cloth
Ceiling Tiles/Lay-in Panels	Electric Wiring Insulation
Sprayed/Blown-in Insulation	Chalkboards
Fireproofing Materials	Roof Shingles/Felts
Taping Compounds	Base Flashing
Wall Packing Materials	Thermal Paper Products
High Temperature Gaskets	Caulking/Putty/Adhesive
Lab Hoods/Benches/Gloves	Wallboard
Fire Blankets/Curtains	Joint/Spackling Compounds
Fire Doors	Vinyl Wall Coverings
Elevator Equipment Panels	